



GEN. TOLERANCES								
	0.5 - 6	±0.1	6 - 30	±0.2	30 - 120	±0.3	120 - 315	±0.5
GEN. MACHINING	✓		1.6	✓	3.2	✓	6.3	✓
							12.6	✓
							25 ROUGH	✓
								✓
								±2
								4000 - 8000
								±3

VIEW ON 'A' SHOWING DRILLING PATTERN AND OTHER DETAILS

[illegible]